

Wiring Diagram N/A  
 Schematic N/A  
 Generator Parts  
 Unassembled 63259-1  
 Complete Unit  
 Part # 63260-1

\*\*\*\*\*  
 \*\* REPAIR \*\*  
 \*\* PARTS LIST \*\*  
 \*\* #762 \*\*  
 \*\*\*\*\*

Size 4000 Watts  
 Drive Direct  
 Type Two Pole  
 Unit Model # 4PTH-3M/L10

<u>DESCRIPTION</u>	<u>PART #</u>	<u>QTY</u>
Armature (less bearing)	62203-1	1
Armature Bearing	55223	1
Armature thru Bolt	23197-7	1
Fan Assy.	55101	1
Fan Washer	23558	1
Fan Lockwasher	55224	1
Fan Nut	23605	1
Field Coil	61960	1
Field Coil	61960-1	1
Shell & Bracket Assy.	63194	1
Pole Shoe	24851	2
Pole Shoe Retainer	63192	2
Engine Adapter Bracket	63393	1
Adapter Bracket Screw	55576	4
End Cover Assy.	55438-12	1
End Cover Receptacle	63269	1
End Cover Receptacle (230V)	55253	1
Brush Rack Assy.	63214	1
Brush Rack	62116	1
A.C. Brush	23607	3
A.C. Brush Holder	59690	3
A.C. Condenser	41221	2
Barrier Spacer	59688	5
Cradle	63190	1
Rubber Feet	23770	1
Rectifier	61663	1

Engine Make Tecumseh Model # HM80 Part # 63394