

Wiring Diagram N/A
 Schematic N/A
 Generator Parts
 Unassembled 63264-1
 Complete Unit
 Part # 63265-1

 ** REPAIR **
 ** PARTS LIST **
 ** #761 **

Size 4000 Watts
 Drive Direct
 Type Two Pole
 Unit Model # 4PTH-3E/L9

<u>DESCRIPTION</u>	<u>PART #</u>	<u>QTY.</u>
Armature (less bearing)	62199-1	1
Armature Bearing	55223	1
Armature thru Bolt	23197-7	1
Fan Assy.	55101	1
Fan Washer	23558	1
Fan Lockwasher	55224	1
Fan Nut	23605	1
Field Coil	61087	1
Field Coil	61087-1	1
Shell & Bracket Assy.	63194	1
Pole Shoe	24851	2
Pole Shoe Retainer	63192	2
Engine Adapter Bracket	63393	1
Adapter Bracket Screw	55576	4
End Cover Assy.	55438-11	1
End Cover Receptacle	63269	1
End Cover Receptacle (230V)	55253	1
Brush Rack Assy.	63216	1
A.C. Brush	23607	3
A.C. Brush Holder	59690	3
D.C. Brush	41393	2
D.C. Brush Holder	41106	1
& Plate Assy.	40894	2
A.C. Condenser	41221	2
D.C. Condenser	41180	1
Resistor Assy. (Charge)	24236	1
Barrier Spacer	59688	5
Cradle	63190	1
Lug	49426	1
Starter Switch	2210	1
Rubber Feet	23770	4

Engine Make Tecumseh Model # HM80 Part # 93394



225 South Cordova Avenue
 Le Center, MN 56057 • (612) 357-6821