


9976-1



NOTES:  
 1. INSTALL ITEM ⑦ FROM GENERATOR FRAME TO CABINET LEG.

92668-1

8	91215-17	1	LEADWIRE ASSY
9	95231	1	GROUND STRAP ASSY
10	94378	1	INSULATED STANDOFF
11	49975	AR	CABLE TIE
12	451837-1	3	LUG
13	7717	2	LUG
14	91215-17	1	LEADWIRE ASSY
15	91215-17	1	LEADWIRE ASSY

DRAWN BY D.M.W.		DATE 2-23-84	CHKD BY RN	DATE	APPR BY RN	DATE 6-25-84	SCALE
MATERIAL		WIRING DIAGRAM TERMINATION ASSY		ORIGINAL		WINCO	