

MODEL CSA3BS-1M PART NO. 58930-1 WIRING DIAGRAM _____

ENGINE _____

WATTS 3000 VOLT 115 AMP 26 PH 1 HZ 60 RPM 1800 INS. A

Ref. No.	Description	Qty	Part No.	Ref. No.	Description	Qty	Part No.
	Armature	1	58287-1				
	Armature Bearing	1	55223				
	Armature Thru Bolt	1	23197-7				
	Fan Ass'y	1	55101				
	Fan Washer	1	23558				
	Fan Lockwasher	1	55224				
	Fan Nut	1	23605				
	Shell & Bracket Ass'y	1	58634				
	Pole Shoe	4	40091				
	Pole Shoe Retainer	4	40092				
	Field Coil	1	58218				
	Field Coil	1	58218-1				
	Field Coil	1	58218-2				
	Field Coil	1	58218-3				
	End Bracket (eng)	1	24211-1				
	End Cover Ass'y	1					
	Brush Holder & Rack Ass'y	1	58290				
	A.C. Brush	4	23607				
	A.C. Brush Holder	4	23500				
	A.C. Capactor	1	54977				
	Rectifier	1	55143				
	Control Box Ass'y	1	58527				
	Receptacle	1	57325				
	Receptacle Duplex	1	24749				
	Receptacle	2	56281				
	Voltmeter	1	52490				
	Enclosed Fuse Cutout	4	8818				
	Fuse 20 Amp	4	47490				
	Fuse Post	2	2489				
	Fuse 15 AMP	2	45722				